

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON
Division Director

OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE
Lieutenant Governor

Lieutenani Gerenien

Representatives Present During the Inspection:

Company Vicky S. Miller Environmental Specialist

Inspection Report

Permit Number:	C0070018	
Inspection Type:	COMPLETE	
Inspection Date:	Thursday, December 18, 2003	
Start Date/Time:	12/18/2003 9:30:00 AM	
End Date/Time:	12/18/2003 10:30:00 AM	
Last Inspection:	Thursday, September 18, 2003	

Inspector: Dana Dean, Environmental Scientist III

Weather: <u>cool ~35 degrees, sunny</u> InspectionID Report Number: <u>128</u>

Accepted by: dhaddock 12/23/2003

Permitee: CANYON FUEL COMPANY LLC Operator: CANYON FUEL COMPANY LLC

Site: SOLDIER CANYON MINE

Address: PO BOX 1029, WELLINGTON UT 84542

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages		Mineral Ownership	Types of Operations		
6,624.64	Total Permitted	☐ Federal	☐ Underground		
24.32	Total Disturbed	☐ State	Surface		
	Phase I	☐ County	Loadout		
	Phase II	☐ Fee	Processing		
	Phase III	Other	Reprocessing		

Report summary and status for pending enforcement actions, permit conditions, Divison Orders, and amendments:

Inspector's Signature:

Date

Thursday, December 18, 2003

Dana Dean, Environmental Scientist III

Inspector ID Number: 50

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining



Permit Number: C0070018 Inspection Type: COMPLETE

Inspection Date: Thursday, December 18, 2003

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENT

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	\checkmark		✓	
2.	Signs and Markers	✓			
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures		✓		
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations	✓		✓	
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches		✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments		✓		
8.	Noncoal Waste	✓		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓			
10.	Slides and Other Damage		✓		
11.	Contemporaneous Reclamation		✓		
12.	Backfilling And Grading		✓		
13.	Revegetation	✓		✓	
14.	Subsidence Control		✓		
15.	Cessation of Operations	✓		✓	
16.	a Roads: Construction, Maintenance, Surfacing	✓			
16.	b Roads: Drainage Controls	✓			
17.	Other Transportation Facilities	✓			
18.	Support Facilities, Utility Installations	✓			
19.	AVS Check	✓			
20.	Air Quality Permit	✓		✓	
21.	Bonding and Insurance	✓		✓	
22.	Other	✓		~	

Page 2 of 4

Permit Number: C0070018
Inspection Type: COMPLETE

Inspection Date: Thursday, December 18, 2003 Page 3 of 4

1. Permits, Change, Transfer, Renewal, Sale

The Division is currently reviewing one amendment to the Soldier Canyon MRP which proposes changes in Chapters 2 and 3.

3. Topsoil

The Permittee reseeded the topsoil pile on November 25th.

4.a Hydrologic Balance: Diversions

The diversions were spot-checked and should function as designed.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Ms. Vicky Miller conducted the third quarter sediment pond inspection on September 17, 2003. She did not note any hazards or instability and the sediment was well below the cleanout marker. There was about 8" of water in the pond.

4.d Hydrologic Balance: Water Monitoring

The Permittee submitted the third quarter water monitoring information on October 14, 2003. They submitted the second quarter information on August 26, 2003.

4.e Hydrologic Balance: Effluent Limitations

The Permittee provided hard copies of the DMR's for review. There was no water discharged from the site during the third quarter.

8. Noncoal Waste

The disturbed area was generally clear on non-coal waste.

13. Revegetation

The Permittee reseeded the topsoil pile on November 25th.

15. Cessation of Operations

The Soldier Canyon Mine is in temporary cessation.

20. Air Quality Permit

The Division of Air Quality issued an Air Quality permit on April 25, 1994.

21. Bonding and Insurance

The Permittee has the site bonded for \$3,238,000 through Liberty Mutual Insurance Company.

Permit Number: C0070018
Inspection Type: COMPLETE

Inspection Date: Thursday, December 18, 2003

Page 4 of 4

22. Other

The Permittee has a Storm Water Pollution Prevention Plan (SWPPP) on-site. As part of their Storm Water Permit, the Permittee was required to conduct quarterly storm water inspections this year (2nd yr. of permit) and write up the results in a storm water discharge monitoring report (SWDMR) to be kept on-site. The Permittee did the inspections as required and the SWDMR's are on-site.